

WELL LOG AND DRILLING REPORT

674304

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

Permit Number 71142

COUNTY Shelby TOWNSHIP Juanine SECTION OF TOWNSHIP 16

OWNER Cyril Bergman ADDRESS 2931-5th Rd, 47

LOCATION OF PROPERTY lot #103 - Conny Wagner Sunny 4375-5th Rd, 48

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 1/2 Length of casing 104 Test rate 10 gpm Duration of test 3 hrs
Type of screen — Length of screen — Drawdown 5 ft Date 6/25/1988
Type of pump — Static level (depth to water) 50 ft
Capacity of pump — Quality (clear, cloudy, taste, odor) Clear
Depth of pump setting — Pump installed by —
Date of completion —
Rotary ☐ or Cable ☐

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

W

E

S

* If additional space is needed to complete well log, use next consecutively numbered form.

DNR 7802

DRILLING FIRM Bergman REGISTRATION NUMBER 1452 DATE 6/25/1988

ADDRESS 7381 5th Rd, 46, Ft. Juana, Ohio SIGNED Jerome J. Bergman

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion.

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy