

WELL LOG AND DRILLING REPORT

674305

NO CARBON PAPER
NECESSARY -
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

Permit Number 71141

COUNTY Shelby TOWNSHIP Jerome SECTION OF TOWNSHIP 16

OWNER Cyril Bergman ADDRESS 2931 St. Rt. 47

LOCATION OF PROPERTY Lot #102-Conn. Wagner Survey- 4427 St. Rt. 48

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST (specify one by circling)

Casing diameter 5 1/2 Length of casing 94
Type of screen — Length of screen —
Type of pump —
Capacity of pump —
Depth of pump setting —
Date of completion —
Rotary ☐ or Cable ☐

Test rate 10 gpm Duration of test 3 hrs
Drawdown 5 ft Date 6/26/1988
Static level (depth to water) 50' ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by —

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale, limestone, gravel, clay	From	To	Locate in reference to numbered state highways, street intersections, county roads, etc.
<u>Clay</u>	<u>0 ft</u>	<u>60 ft</u>	
<u>Sand</u>	<u>60</u>	<u>94</u>	
<u>Gravel</u>	<u>94'</u>		

* If additional space is needed to complete well log, use next consecutively numbered form.

DNR 7802

DRILLING FIRM Bergman REGISTRATION NUMBER 1452 DATE 6/26/1988

ADDRESS 7381 St. Rt. 66, Ft. Jennings, O. SIGNED Jerome J. Bergman

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue - Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy