

WELL LOG AND DRILLING REPORT

676435

NO CARBON PAPER
NECESSARY-
SELF-TRANSCRIBING

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Fountain Square
Columbus, Ohio 43224

Permit Number 496-90

COUNTY Morrow TOWNSHIP Lincoln SECTION OF TOWNSHIP _____
OWNER James E. Blin ADDRESS 3835 CR-25 Cardington
LOCATION OF PROPERTY 3835 CR-25 Ohio 43315

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

(specify one by circling)

Casing diameter 5 1/2 Length of casing 40
Type of screen NONE Length of screen _____
Type of pump submersible
Capacity of pump _____
Depth of pump setting 30 ft
Date of completion 7-9-90
Rotary ☒ or Cable ☒

Test rate 5 gpm Duration of test 10 hrs
Drawdown 0 ft Date 6-30-90
Static level (depth to water) 20 ft
Quality (clear, cloudy, taste, odor) clear
Pump installed by Dupe Drilling

WELL LOG*

SKETCH SHOWING LOCATION

Formations: sandstone, shale,
limestone, gravel, clay

From

To

Locate in reference to numbered
state highways, street intersections, county roads, etc.

Clay

0 ft

30 ft

Sand

30

35

Gray shale

35

40

sand & gravel

40

45

Water at 40

W

N

CR-25

E

S

* If additional space is needed to complete well log, use next consecutively numbered form.

DNR 7802

DRILLING FIRM Dupe Drilling REGISTRATION NUMBER 01893 DATE 7-9-90

ADDRESS 3350 CR 170 Cardington SIGNED R L Lantier

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion.

WHITE ORIGINAL COPY - ODNR, DIVISION OF WATER, FOUNTAIN SQ., COLS., OHIO 43224 / Blue - Customer's Copy / Pink - Driller's Copy / Green - Local Health Dept. Copy