

WELL LOG AND DRILLING REPORT

695553

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1939 Fountain Square Drive
Columbus, Ohio 43224
(614) 265-6739

TYPE OR USE PEN
SELF-TRANSCRIBING
PRESS HARD!

Permit Number #95454

COUNTY Medina TOWNSHIP Trarvers SECTION/LOT NO. _____
(CIRCLE ONE)
OWNER/BUILDER Bob Zimmerman PROPERTY ADDRESS 1607 Akron Peninsula Rd.
(CIRCLE ONE OR BOTH) (ADDRESS OF WELL LOCATION 1)
LOCATION OF PROPERTY 1730 N. Medina Line Rd.

CONSTRUCTION DETAILS

CASING
Diameter 5" in. Length 167 ft. Wall Thickness 244 in.
Type: ☒ Steel ☐ Galv. ☐ PVC ☐ Other _____
Joints: ☐ Threaded ☐ Welded ☐ Solvent ☐ Other _____
SCREEN
Type (wire wrapped, louvered, etc.) none Material _____
Length _____ ft. Diameter _____ in.
Set between _____ ft. and _____ ft. Slot _____
☐ Rotary ☒ Cable ☐ Augered ☐ Driven ☐ Dug ☐ Other _____
Date of completion June 20/89
GROUT
Material sand clay grout Volume used _____
Method of installation hydraulic
Depth: placed from _____ ft. to 160' ft.
GRAVEL PACK
Material _____ Volume used _____
Method of installation _____
Depth: placed from _____ ft. to _____ ft.
Pitless Device ☐ Adapter ☐ Preassembled unit
Use of Well _____

PUMP
Type of pump _____ Capacity _____ gpm
Pump set at _____ ft.
Pump installed by _____

WELL TEST
Bailing ☒ or Pumping ☐
Test rate 20 gpm Duration of test 6 hrs.
Drawdown 12 ft.
Measured from: ☐ top of casing ☒ ground level ☐ Other _____
Static Level (depth to water) 60 ft. Date: 6/20/89
Quality (clear, cloudy, taste, odor) clear
(Attach a copy of the pumping test record, per 1521.05, ORC)

WELL LOG*		
INDICATE DEPTH(S) AT WHICH WATER IS ENCOUNTERED.		
Show color, texture, hardness, and formation: sandstone, shale, limestone, gravel, clay, sand, etc.	From	To
<u>X clay</u>	<u>0 ft.</u>	<u>10'</u>
<u>broken clay</u>	<u>10'</u>	<u>14'</u>
<u>yellow clay & gravel</u>	<u>14'</u>	<u>21'</u>
<u>blue clay</u>	<u>21'</u>	<u>40'</u>
<u>blue clay & gravel</u>	<u>40'</u>	<u>74'</u>
<u>blue clay</u>	<u>74'</u>	<u>113'</u>
<u>blue clay & gravel</u>	<u>113'</u>	<u>142'</u>
<u>broken shale</u>	<u>142'</u>	<u>155'</u>
<u>broken sandstone</u>	<u>155'</u>	<u>162'</u>
<u>broken shale</u>	<u>162'</u>	<u>167'</u>
<u>shale</u>	<u>167'</u>	<u>178'</u>
<u>water at 175'</u>		

SKETCH SHOWING LOCATION
Show distances well lies from numbered
state highways, street intersections, county roads, etc.

* If additional space is needed to complete well log, use next consecutively numbered form

DRILLING FIRM Steve Alchier
ADDRESS 923 W. Turkeyfoot
CITY, STATE, ZIP Akron Ohio 44319

SIGNED Steve Alchier
DATE 6/20/89
ODH REGISTRATION NUMBER 213

DNR 7802.88

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion of drilling.

ORIGINAL COPY - ODNR, DIVISION OF WATER, 1939 FOUNTAIN SQ. DRIVE, COLS., OHIO 43224

Blue - Customer's Copy Pink - Driller's Copy Green - Local Health Dept. Copy