

WELL LOG AND DRILLING REPORT

Homeowner
707884

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
1939 Fountain Square Drive
Columbus, Ohio 43224
(614) 265-6739

TYPE OR USE PEN
SELF-TRANSCRIBING
PRESS HARD!

Permit Number _____

COUNTY Fulton TOWNSHIP German SECTION/LOT NO. #3 Lot
OWNER/BUILDER Lawrence / Margaret Frame PROPERTY ADDRESS 6810 G Rd 26 Archbold, Ohio
(CIRCLE ONE OR BOTH) (ADDRESS OF WELL LOCATION 1) 43502
LOCATION OF PROPERTY _____

CONSTRUCTION DETAILS

CASING
Diameter 4 in. Length 95 ft. Wall Thickness 1/4 in.
Type: ☐ Steel ☐ Galv. ☒ PVC ☐ Other _____
Joints: ☐ Threaded ☒ Welded ☐ Solvent ☐ Other _____
SCREEN
Type (wire wrapped, louvered, etc.) louvered Material PVC
Length 10 ft. Diameter 4 in.
Set between 95 ft and 85 ft. Slot 1/4 inch
☐ Rotary ☐ Cable ☐ Augered ☐ Driven ☐ Dug ☐ Other drilled
Date of completion 90 feet (1985) - 5400 ft (Nov. 1989)

GROUT
Material _____ Volume used _____
Method of installation drilled & Deep Rock drilling method
Depth: placed from _____ ft. to _____ ft.
GRAVEL PACK
Material _____ Volume used _____
Method of installation _____
Depth: placed from _____ ft. to _____ ft.
Pitless Device ☐ Adapter ☐ Preassembled unit
Use of Well _____

PUMP
Type of pump 3 HP Harsco Capacity _____ gpm
Pump set at approx 47 ft.
Pump installed by Self

WELL TEST
Bailing ☐ or Pumping ☐
Test rate _____ gpm Duration of test _____ hrs.
Drawdown _____ ft.
Measured from: ☐ top of casing ☐ ground level ☐ Other _____
Static Level (depth to water) _____ ft. Date: _____
Quality (clear, cloudy, taste, odor) taste iron
(Attach a copy of the pumping test record, per 1521.05, ORC)

WELL LOG*

INDICATE DEPTH(S) AT WHICH WATER IS ENCOUNTERED.


Show color, texture, hardness, and formation:

sandstone, shale, limestone, gravel, clay, sand, etc.

	From	To
Dark Brown Clay	0 ft.	1 ft.
Lighter Brown clay	1 ft.	3 ft.
Blue Gray clay	3 ft.	5 1/2 - 6 ft.
Varied from ^{apparently} it clay Brown to Md. Br.	6 ft.	80 ft.
We apparently hit some small streaming but no apparent sand		
at 80 ft. hit a rock which deviated the well poss. south or	80 ft.	
south east?		
apparently clay Brown	80 ft.	89 ft.
hit fine Sand/Water overflow. 90 -		
Pushed pipes (4 in well) down 4 or 5 feet - hit coarse Sand	94 - 95 ft.	
Well overflows w/ water		
We used too much Mud Pack - unable to be sure of soil & color.		

SKETCH SHOWING LOCATION

Show distances well lies from numbered
state highways, street intersections, county roads, etc.



* If additional space is needed to complete well log, use next consecutively numbered form

DNR 7802.88

DRILLING FIRM Self
ADDRESS 6810 G Rd 26
CITY, STATE, ZIP Archbold, Ohio 43502

SIGNED Margaret Frame
DATE 7-
ODH REGISTRATION NUMBER _____

Completion of this form is required by 1521.05, Ohio Revised Code - file within 30 days after completion of drilling.

ORIGINAL COPY - ODNR, DIVISION OF WATER, 1939 FOUNTAIN SQ. DRIVE, COLS., OHIO 43224

Blue - Customer's Copy Pink - Driller's Copy Green - Local Health Dept. Copy