

WELL LOG AND DRILLING REPORT

LOCATED

NO. 7355920

County Wood Township Henry Section of Township 29
 Owner Frank Claybaugh Address N. Baltimore
 Location of property 3 mi W of N Baltimore on J.Rt 10

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 1/4 Length of casing 67 Pumping rate 15 G.P.M.
 Type of screen _____ Length of screen _____ Duration of test 1/2 hrs.
 Type of pump hand Drawdown 0 ft. Date 11-30-48
 Capacity of pump 10/min Developed capacity _____
 Depth of pump setting 20 Static level - depth to water 0 ft.
 Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation

From

To

N.

clay

0

15

bl. clay

40

s. + g.

65

rock

72

W.

drilled ^{10'} deeper 9-24-49

Bailer test

30 - gpm

1/2 - hr.

S.L. - 24'

casing - 5 5/8

S.

Drilling Firm J. E. King & SonDate 12-19-60

Address _____

Copied by ES20