

WELL LOG AND DRILLING REPORT

Ohio Department of Natural Resources
Division of Water, 1939 Fountain Square Drive
Columbus, Ohio 43224 Phone (614) 265-6739

796839

Permit Number 1762

COUNTY Stark TOWNSHIP Oshtaburg SECTION/LOT No. 27
(Circle One)
OWNER/BUILDER Lee Sternberg PROPERTY ADDRESS 7076 mapleton St E Canton
(Circle One or Both) First Last (Address of well location) Number Street City

LOCATION OF PROPERTY APPROX. 1 m. W. OF RT. 44 (NEAR E. CANTON) Zip Code + 4

CONSTRUCTION DETAILS

CASING (Length below grade) Borehole Diameter 7 7/8 in.
[1] Diameter 5 in. Length 246.5 ft. Wall Thickness SPR 21 in. Material E-Z mud lens seal Volume used 25 gal 10 bags
[2] Diameter _____ in. Length _____ ft. Wall Thickness _____ in. Method of installation friction
Type: [1] Steel [1] Galv. [X] PVC [1] _____
[2] _____ [2] _____ [2] _____
Joints: [1] Threaded [1] Welded [X] Solvent [1] _____
[2] _____ [2] _____ [2] _____
Liner: Length _____ Type _____ Wall Thickness _____ in. Depth: placed from _____ ft. to _____ ft.
SCREEN
Type (wire wrapped, louvered, etc.) _____ Material _____
Length _____ ft. Diameter _____ in.
Set between _____ ft. and _____ ft. Slot _____
Pitless Device [X] Adapter [] Preassembled unit
Use of Well RESIDENTIAL
[X] Rotary [] Cable [] Augered [] Driven [] Dug [] Other _____
Date of Completion _____

WELL LOG*

INDICATE DEPTH(S) AT WHICH WATER IS ENCOUNTERED.

Show color, texture, hardness, and formation:
sandstone, shale, limestone, gravel, clay, sand, etc.

	From	To
Soft gr Sandrock	0	46
dk shale	46	54
coal	54	55
Fire clay	55	60
hard gr Sandrock	60	99
hard gr limestone	99	100
hard gr Sandstone	100	133
hard gr limestone	133	134
hard gr shale	134	150
hard gr limestone	150	153
hard coal	153	155
gr shale	155	161
hard gr Sandrock	161	175
hard gr Sandstone	175	208
hard gr limestone	208	210
white Sandrock w shale	210	235
lt gr shale	235	239
hard gr Sandstone w Sandrock	239	281
hard lt gr Sandstone w lime	281	305
white Sandrock w shale	305	362

WELL TEST

[] Bailing [] Pumping* [X] Other AIR
Test rate 25 gpm Duration of test 2 hrs.
Drawdown 129 ft.
Measured from: [] top of casing [X] ground level [] Other 8/15/94
Static Level (depth to water) 171 ft. Date: _____
Quality (clear, cloudy, taste, odor) CLEAR

*(Attach a copy of the pumping test record, per section 1521.05, ORC)

PUMP

Type of pump 1.5 H.P. SUBGS Capacity 10 gpm
Pump set at 300 ft.
Pump installed by DAVIDSON'S

WELL LOCATION

Location of well in State Plane coordinates, if available:
Zone _____ x _____ y _____
Elevation of well _____ ft./m. Datum plain: [] NAD27 [] NAD83
Source of coordinates: [] GPS [] Survey [] Other _____
Sketch a map showing distance well lies from numbered state highways,
street intersections, county roads, buildings or other notable landmarks.

North
362-386 black slate
386-391 white Sandrock
391-449 dk gr. Sandstone
449-483 white Sandrock w water
T.D. MAPLETON ST.
WELL IS 28' FROM HOUSE
WELL @ South
SEPTIC
NEW HOME

(If additional space is needed to complete well log, use next consecutively numbered form.)

I hereby certify the information given is accurate and correct to the best of my knowledge.

Drilling Firm Davidson Well Drilling
Address 3160 Beechwood Ave.

Signed John Davidson
Date 8/19/94

City, State, Zip Albion, Ohio 44601

ODH Registration Number 506

Completion of this form is required by section 1521.05, Ohio Revised Code - file within 30 days after completion of drilling.
ORIGINAL COPY TO - ODNR, DIVISION OF WATER, 1939 FOUNTAIN SQ. DRIVE, COLS., OHIO 43224

Blue - Customer's copy Pink - Driller's copy Green - Local Health Dept. copy