

# WELL LOG AND DRILLING REPORT

Ohio Department of Natural Resources  
Division of Water, 1939 Fountain Square Drive  
Columbus, Ohio 43224 Phone (614) 265-6739

811007

Permit Number 4057

COUNTY Stark TOWNSHIP Osnaburg SECTION/LOT No. \_\_\_\_\_  
(Circle One)  
OWNER/BUILDER Jerry Linky PROPERTY ADDRESS 2281 Belfort St. S.E. East Canton  
(Circle One or Both) First Last (Address of well location) Number Street City  
LOCATION OF PROPERTY 1/4 mile off State Route 172 on Belfort St. Zip Code + 4 \_\_\_\_\_

## CONSTRUCTION DETAILS

CASING (Length below grade) Borehole Diameter drone Pipe 1/8 GROUT  
[1] Diameter 8 1/2 in. Length 31 ft. Wall Thickness 1/8 in. Material drone Pipe Volume used \_\_\_\_\_  
[2] Diameter \_\_\_\_\_ in. Length \_\_\_\_\_ ft. Wall Thickness \_\_\_\_\_ in. Method of installation \_\_\_\_\_  
Type: [1] Steel [1] Galv. [1] PVC [1] \_\_\_\_\_  
[2] Other \_\_\_\_\_  
GRAVEL PACK (Filter Pack)  
Material \_\_\_\_\_ Volume used \_\_\_\_\_  
Method of installation \_\_\_\_\_  
Joints: [1] Threaded [1] Welded [1] Solvent [1] \_\_\_\_\_  
[2] Other \_\_\_\_\_  
Liner: Length \_\_\_\_\_ Type \_\_\_\_\_ Wall Thickness \_\_\_\_\_ in. Depth: placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
SCREEN  
Type (wire wrapped, louvered, etc.) \_\_\_\_\_ Material \_\_\_\_\_  
Length \_\_\_\_\_ ft. Diameter \_\_\_\_\_ in.  
Set between \_\_\_\_\_ ft. and \_\_\_\_\_ ft. Slot \_\_\_\_\_  
Use of Well  
[ ] Rotary [x] Cable [ ] Augered [ ] Driven [ ] Dug [ ] Other \_\_\_\_\_  
Date of Completion Aug 27 1996

## WELL LOG\*

INDICATE DEPTH(S) AT WHICH WATER IS ENCOUNTERED.

Show color, texture, hardness, and formation:  
sandstone, shale, limestone, gravel, clay, sand, etc.

|                   | From | To  |
|-------------------|------|-----|
| Top soil          | 0    | 1   |
| yellow sandy clay | 1    | 15  |
| sand              | 15   | 30  |
| gravel            | 30   | 35  |
| gray soft clay    | 35   | 50  |
| sand stone        | 51   | 75  |
| gray shell        | 75   | 100 |

water encountered 75'

## WELL TEST

[x] Bailing [ ] Pumping\* [ ] Other \_\_\_\_\_  
Test rate 10 gpm Duration of test 1/2 hrs.  
Drawdown 10' ft.  
Measured from: [x] Top of casing [ ] ground level [ ] Other \_\_\_\_\_  
Static Level (depth to water) 40 ft. Date: Aug 22 1996  
Quality (clear) cloudy, taste, odor \_\_\_\_\_

\*(Attach a copy of the pumping test record, per section 1521.05, ORC)


## PUMP

Type of pump Aermotor Capacity 12 gpm  
Pump set at 75' ft.  
Pump installed by Floyd Lancaster

## WELL LOCATION

Location of well in State Plane coordinates, if available:  
Zone \_\_\_\_\_ x \_\_\_\_\_ y \_\_\_\_\_  
Elevation of well \_\_\_\_\_ ft./m. Datum plain: [ ] NAD27 [ ] NAD83  
Source of coordinates: [ ] GPS [ ] Survey [ ] Other \_\_\_\_\_

Sketch a map showing distance well lies from numbered state highways, street intersections, county roads, buildings or other notable landmarks.



\*(If additional space is needed to complete well log, use next consecutively numbered form.)

I hereby certify the information given is accurate and correct to the best of my knowledge.

Drilling Firm Floyd's Water Well Drilling  
Address 2056 Ravenna ave. S.E.  
City, State, Zip East Canton Ohio 44730

Signed Floyd Lancaster  
Date Aug 31 1996  
ODH Registration Number 02058