

WELL LOG AND DRILLING REPORT

State of Ohio
Department of Natural Resources
Division of Water
1562 W. First Avenue
Columbus, Ohio

22
88766
NO. ~~1517~~
LOCATED

County FRANKLIN Township MIFFLIN Section of Township _____
Owner E. R. CHERRY Address 2705 Sunbury Dr.
Location of property SAME

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 5 Length of casing 32 Pumping rate 10 G.P.M.
Type of screen _____ Length of screen _____ Duration of test $\frac{1}{2}$ Hrs.
Type of pump _____ Drawdown _____ ft. Date _____
Capacity of pump _____ Static level - depth to water 6 Ft.
Depth of pump setting _____ Quality _____
Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation	From	To	N.	E.	S.	W.
Dirt	0	15				
Sandy clay	15	26				
Sandy gravel	26	32				

Drilling Firm H. J. May Date _____
Address _____ Copied by RH 11/5/64

209