

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

✓ 1518
No 88767

County Franklin Township Mellen Section of Township
or Lot Number
Owner E C Miller Address 802 S Washington St
Circleville O
Location of property 3144 Ogden Rd

CONSTRUCTION DETAILS

Casing diameter 5" Length of casing 97
Type of screen Painland Length of screen 5'
Type of pump
Capacity of pump
Depth of pump setting

PUMPING TEST


Pumping rate 10 G.P.M. Duration of test 1 hrs.
Drawdown ft. Date
Developed capacity
Static level—depth to water 65 ft.
Pump installed by

WELL LOG

Formations Sandstone, shale, limestone, gravel and clay	From	To
	0 Feet	 Ft.
<u>Fill dirt</u>		<u>15</u>
<u>Sandy Clay</u>	<u>15</u>	<u>90</u>
<u>Sand and Gravel</u>	<u>90</u>	<u>97</u>

SKETCH SHOWING LOCATION

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.



Drilling Firm H J May

Date Oct 6-51

Address Reynoldsburg O

Signed H J May