

WELL LOG AND DRILLING REPORT

Ohio Department of Natural Resources
Division of Water, 1939 Fountain Square Drive
Ohio 43224-9971 Voice (614) 265-6739 Fax (614) 447-9503

901808

CONSTRUCTION DETAILS	
<i>East</i> <i>SRP</i> <i>NE</i> <i>43945</i> <i>28</i> <i>well</i> <i>awell</i> <i>April</i> <i>Chemistown</i> <i>12/30/99</i> <i>7</i> <i>7</i> <i>12/30/99</i>	☐ Rotary ☒ Cable ☐ Augered ☐ Driven ☐ Other _____ BOREHOLE/CASING (measured from ground surface) 1 ☐ Borehole Diameter <u>7</u> inches Depth <u>39</u> ft. Casing Diameter <u>5 1/4</u> in. Length <u>44 1/2</u> ft. Thickness <u>2 1/4</u> in. 2 ☐ Borehole Diameter _____ inches Depth _____ ft. Casing Diameter _____ in. Length _____ ft. Thickness _____ in. Casing Height Above Ground <u>2</u> ft. Type 1 ☒ Steel 1 ☐ Galv. 1 ☐ PVC 1 ☐ 2 ☐ 2 ☐ 2 ☐ 2 ☐ Other _____ Joints 1 ☐ Threaded 1 ☐ Welded 1 ☐ Solvent 1 ☐ 2 ☐ 2 ☐ 2 ☐ 2 ☐ Other _____ SCREEN Diameter _____ Slot Size _____ Screen Length _____ ft. Type _____ Material _____ Set Between _____ ft. and _____ ft. GRAVEL PACK (Filter Pack) Material/Size _____ Volume/Weight Used _____ Method of Installation _____ Depth: Placed FROM _____ ft. TO _____ ft. GROUT Material <u>Drill Cuttings</u> Volume/Weight Used _____ Method of Installation _____ Depth: Placed FROM _____ ft. TO _____ ft.
DRILLING LOG*	
INDICATE DEPTH(S) AT WHICH WATER IS ENCOUNTERED.	
Show color, texture, hardness, and formation: sandstone, shale, limestone, gravel, clay, sand, etc.	From
	To
<u>Soil</u>	<u>0</u>
<u>Brown Shale</u>	<u>1</u>
<u>Light Gray Shale</u>	<u>17</u>
<u>Dark Gray Shale</u>	<u>37</u>
<u>Lime Rock</u>	<u>76</u>
<u>Dark Shale</u>	<u>92</u>
<u>Limey</u>	<u>110</u>
	<u>122</u>

by section 1521.05, Ohio Revised Code - file within 30 days after completion of drilling.
DIVISION OF WATER, 1939 FOUNTAIN SQ. DRIVE, COLS., OHIO 43224-9971
Customer's copy Pink - Driller's copy Green - Local Health Dept. copy