

WELL LOG AND DRILLING REPORT

ORIGINAL

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio

No. 91086

(18)

County Washington Township Muskingum Section of Township
or Lot Number

Owner L. A. Duckworth Address Rt 3, Marietta, Ohio

Location of property North of Marietta on U.S. Rt 21

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 5.5/8 Length of casing 17' 4"

Type of screen Length of screen

Type of pump

Capacity of pump

Depth of pump setting Not Set

Pumping rate G.P.M. Duration of test hrs.

Drawdown ft. Date

Developed capacity

Static level—depth to water 17' ft.

Pump installed by

WELL LOG

SKETCH SHOWING LOCATION

Formations
Sandstone, shale, limestone,
gravel and clay

From

To

0 Feet

.....Ft.

Clay

0

15

Creek Sand

15

16

Sand Hard

16

24

Shale

24

28

Sand

28

35

Shale

35

43

Lime

43

Locate in reference to numbered
State Highways, St. Intersections, County roads, etc.

N.

Well----

E.

U.S. 77