

WELL LOG AND DRILLING REPORT

State of Ohio
DEPARTMENT OF NATURAL RESOURCES
Division of Water
Columbus, Ohio



No. 93950

JWC ORIGINAL
1404

County Mahoning Township Boardman Section of Township _____ Lot Number _____
Owner Mr. Frank Boardman Address 4516 Lake Park Rd.
Location of property 4516 Lake Park Rd. - Youngstown - O.

CONSTRUCTION DETAILS

PUMPING TEST

Casing diameter 5 5/8 Length of casing 45' 8" Pumping rate _____ G.P.M. Duration of test _____ hrs.
Type of screen _____ Length of screen _____ Drawdown _____ ft. Date _____
Type of pump _____ Developed capacity _____
Capacity of pump _____ Static level—Depth to water 120 ft.
Depth of pump setting _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formations Sandstone, shale, limestone, gravel and clay	From	To	Locate in reference to numbered State Highways, St. Intersections, County roads, etc.
<u>Drift</u>	<u>0 Feet</u>	<u>15 Ft.</u>	
<u>gray sandstone</u>	<u>15</u>	<u>28</u>	
<u>dark gray shale</u>	<u>28</u>	<u>75</u>	
<u>fine clay</u>	<u>75</u>	<u>78</u>	
<u>gray sandstone</u>	<u>78</u>	<u>95</u>	
<u>gray sandstone</u>	<u>95</u>	<u>120</u>	See reverse side for instructions

Drilling Firm Robert Slaven & Son
Address _____

Date _____
Signed _____

