

9962002

LOCATED

WELL LOG AND DRILLING REPORT

63

NO. _____

County Ottawa Township Benton Section of Township _____
 Owner Raymond Lowe Address R2 Oak Harbor
 Location of property SR 579 + 2

CONSTRUCTION DETAILS

BAILING OR PUMPING TEST

Casing diameter 4 1/4 Length of casing 66 Pumping rate _____ G.P.M.
 Type of screen _____ Length of screen _____ Duration of test _____ hrs.
 Type of pump duro shallow well Drawdown _____ ft. Date _____
 Capacity of pump 350 / hr. Developed capacity _____
 Depth of pump setting 14 Static level - depth to water 8 ft.
 Date of completion _____ Pump installed by _____

WELL LOG

SKETCH SHOWING LOCATION

Formation
 clay loam
 lake sand
 wh. limestone
 water 80'

From	To
0	20
	60
	80
	86

W.

N.

E.

S.

Drilling Firm N.O. Mahan + Son Date 2-26-60
 Address _____ Copied by RS

63